




Wood from
frit pit in
pump.

Recreation of
how Ryan was
standing to
check leak.



Ramp Ryan
escaped up





Fitting



← Groove where
bearings are
designed to rest.

← Bearings



Chip out of
fitting.



Where
disconnect
occured



The Setup

